STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

	Delta		c	COUNTY	
	T	43 N	. R	22 W	
DESCRIPTION OF CORNER 1/4 corner for sections 29				<u> </u>	
CORNER MONUMENT 1" iron pipe with 4" aluminum	caj	<u> </u>			
DATE MONUMENT PLACED AND WITNESSED 6/30/70, F. J. Bray	w.	th M. Con	ley		
WITNESSES TO CORNER 7" S. Maple (1/4 S) (NBT) N 45	۰,	2, 8.9'		<u> </u>	
7" S. Maple (1/4 S) (NBT) S 30	<u>°</u> i	i, 11.8'			
20" Y. Birch (original BT) S 18	3°]	s, 10.5'			
CIRCLE CORNER REGISTERED					

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was shown to me by Forester Conley. Green yellow birch with upper and lower faces chopped out and rotted. No iron marks found. Two wood posts and fence corner with single wire near.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGN

SIGNED Face LAND SURVEYOR

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing DATE _