STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

			DELTA	COUNTY
			T <u>43 I</u>	R22W
DESCRIPTION OF CORNER	Section corner	19/20 30/29		
CORNER MONUMENT 1" iron pipe with 4" aluminum cap				
DATE MONUMENT PLACED AND WITNESSED May 9, 1972				
WITNESSES TO CORNER	4 Cedar (S.20)	(nbt) n76°E 1	8.51	<u> </u>
N	4 Cedar (S.30)	(NBT) S80 ⁰ W 3	3.31	
	AND			
CIRCLE CORNER REGISTERED	D			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by double proportionate measurement from the section corners one mile to the south, one mile to the north, one mile to the west and 1/4 corner 1/2 mile to the east.

SURVEYOR'S SEAL

SIGNED

ED PROTETERED LAND SURVEYOR

DATE

6**-1**9-72

DISTRIBUTION:

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing