STATE OF MICHIGAN DEPARTMENT 0F NATURAL RESOURCES

LAND CORNER RECORD

	DEI	TA COUNTY
	T <u>43</u>	N R 22 W
DESCRIPTION OF CORNER	1/h corner for Sections 30	
CORNER MONUMENT	1" iron pipe with 4" aluminum cap	
DATE MONUMENT PLACED AND WITNESSED May 10, 1972		
WITNESSES TO CORNER	5" Cedar (1/1 S) (NBT) S32°E 18.0'	
N	6" Cedar (1/4 S) (NBT) N52°E 36.3'	
	AND	
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportions on line between the sections corners to the east and to the west.

SURVEYOR'S SEAL

REGISTERED LAND SURVEYOR

DATE

DISTRIBUTION:

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing