

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


DELTA COUNTY  
T 43 N R 22 W

DESCRIPTION OF CORNER East 1/16 for Sections <sup>19</sup>/<sub>30</sub>

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED May 10, 1972

WITNESSES TO CORNER..... 3 Cedar (E 1/16) (BT) N03°E 5.4'



4 Cedar (E 1/16) (BT) N83°E 5.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportions on line between the section corner to the east and 1/4 corner to the west.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED Frank J. Bray DATE 6-19-72  
REGISTERED LAND SURVEYOR  
Frank J. Bray

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68