

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


DELTA COUNTY
T 43 N R 22 W

DESCRIPTION OF CORNER East 1/16 corner for Sections $\frac{11}{14}$

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED May 5, 1972

WITNESSES TO CORNER..... 5" Elm (E 1/16) (BT) N56°E 58.5'



5" H. Maple (E 1/16) (BT) S63°W 60.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set midpoint and on line between the section corner to the east and the 1/4 corner to the west. The corner lies in the southeast corner of field.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Broy
REGISTERED LAND SURVEYOR
Frank J. Broy

DATE

6-19-72

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68