STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		DELTA	COUNTY
		T <u>43 1:</u>	R _22.vl
DESCRIPTION OF CORNER _	North 1/16 corner for Section	s 15/14	
CORNER MONUMENT 1" iron pipe with h" aluminum cap			
DATE MONUMENT PLACED AND WITNESSED May 5, 1972 F. J. Bray			
WITNESSES TO CORNER 4" Cedar (N 1/16) (BT) N63°W 18.5'			
N	5" Cedar (N 1/16) (BT) N20°E	9.91	
	AND		
CIRCLE CORNER REGISTER		DENTIFIED AD	BEATABED.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between the section corner to the north and the 1/4 corner to the south.

SURVEYOR'S SEAL

SIGNED

REGISTERED LAND SURVEYOR

Frank J. Bray

DATE

6-19-72

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor

Forestry Div., Lansing

R 4047 Rev. 10/68