## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

		ALGER, DELTA COUNTY
		T 44 & 43 N R 22 W
DESCRIPTION OF CORNER	East 1/16 corner for Sections	35-2 TU4N-R22W 5235 TU3N-R22W
CORNER MONUMENT 1" iron pipe with 4" aluminum cap		
DATE MONUMENT PLACED AND WITNESSED Nay 8, 1972		
WITNESSES TO CORNER 7" Cedar (E 1/16) (BT) S22°E 3.5'		
N 2	10" R. Maple (E 1/16) (BT) N	3Ц <sup>0</sup> Е 13.71
	AND	
CIRCLE CORNER REGISTERED		

## DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set midpoint and on line between the section corner to the east and the 1/4 corner to the west.

SURVEYOR'S SEAL

SIGNED

REGISTERED LAND SURVEYOR

DATE .

6-19-72

DISTRIBUTION:

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing