## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES



## LAND CORNER RECORD

	Del	taCOUNTY
	T 43 N	R _22 W
DESCRIPTION OF CORNER <u>South 1/16 corner for Sections</u>	35/36	
CORNER MONUMENT 1" iron pipe with 4" aluminum cap		
DATE MONUMENT PLACED AND WITNESSED 9/3/71 F. J. Bra	у	
WITNESSES TO CORNER 6" R. Maple (S1/16) (BT) N	58° W, 23.4	t
7" Cedar (S1/16) (BT) N 60°	E, 9.5'	
AND		
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between the section corner to the south and the 1/4 corner to the north.

SURVEYOR'S SEAL

DISTRIBUTION: SIGN

SIGNED REGISTERED LAND SURVEYOR

DATE \_\_\_\_9-21-71

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68