## STATE OF MICHIGAN DEPARTMENT 0F **NATURAL RESOURCES**

## LAND CORNER RECORD

|                                                      | DeltaCOUNTY   |
|------------------------------------------------------|---------------|
|                                                      | T 43 N R 22 W |
| DESCRIPTION OF CORNER South 1/16 corner for Sections | 34/35         |
| CORNER MONUMENT 1" iron pipe with h" aluminum cap    |               |
| DATE MONUMENT PLACED AND WITNESSED 9/8/71 F. J. Bray |               |
| WITNESSES TO CORNER 11" Elm (S1/16) (BT) N 74° I     | E, 12.5'      |
| N 10" Elm (S1/16) (BT) N 73° V                       | w, 6.4°       |
| AND                                                  |               |
| CIRCLE CORNER REGISTERED                             |               |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between the section corner to the south and the 1/4 corner to the north.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

REGISTERED WAND SURVEYOR

DATE

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68