

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T.43.. NR. 22 W..

Delta COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 5, 6, 7, 8.

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 7" Cedar S 24° W 23 links

12" Cedar N 10° E 11 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner; 3 old Cedar stakes, last one set about 20 years ago. There are good corners. 1/2 mile West and 1/2 mile South. No evidence of original B.T.'s.

There is evidence of considerable work having been done in this area, but no record. This work seems very good.

Corner found by Forestry Division Survey Crew while making a partial re-survey of this area.

Corner placed and witnessed March 27, 1956.

SURVEYORS SEAL

SIGNED

Billy D. Buckles
REGISTERED LAND SURVEYOR

DATE 4/19/56