

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 43. NR 22-23 W.

Delta COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 7, 18, 12, 13.

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap.

WITNESSES TO CORNER 15" W. Pine N 70° W 22 links

10" Cedar N 39° E 30 links

These trees have been marked "B.T." some years ago.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner has been re-nixed by unknown surveyor.

One Hemlock Stp. bottom in proper position.

Corner placed and witnessed August 24, 1955.

SURVEYORS SEAL

SIGNED *Billy D. Buckler* DATE 2/14/56  
REGISTERED LAND SURVEYOR