

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43. NR. 22. W. . .

----- Delta ----- COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 14, 15 -----

DESCRIPTION OF CORNER MONUMENT 1" iron pipe with 4" brass cap -----

WITNESSES TO CORNER 5" Cedar ----- S 7° W 17 1/2 links -----
Marked " 1/4 S " NBT"

9" Cedar ----- N 73° W 25 1/2 links -----
Marked " 1/4 S " NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-established 1/4 Corner Midway and on Line between two Section Corners.

No evidence of original corner.

Corner lies in Cedar Swamp.

Corner placed and witnessed October 31, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 11/21/56