MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T 43 NR 22 W

	Detta	_ COUNTY
DESCRIPTION OF CORNER	1/4 Corner between Sections 17, 18	-
DESCRIPTION OF CORNER	MONUMENT 1" iron pipe with 4" brass cap_	
WITNESSES TO CORNER _	5" Cedar _ S 56° W 55 link	8
	8" Spruce N 75° E NET" - 26 link	8

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 Corner as set by McNabb, County Surveyor.

Found Scribed Post and NBTs:

Distance checks with Corners N - S.

1/4 Corner found by Forestry Division survey crew while making a partial re-survey of this Township.

Corner placed and witnessed December 19, 1956.

SURVEYORS SEAL