

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 NR. 22 W.

Delta COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sec.'s 16-21

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 12" Hemlock S 60° W 22 links

7" Cedar 1/4 S NBT S 30° E 61 1/2 links
1/4 S NBT

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Set 1/4 Corner. Found down cedar squared; Forest Service tag on tree since 1937. Many cruisers names on tree in area dating back to 1927. Old line of blazes east and west from corner. Distance east to stream checks. Found by Forestry Division Survey Crew. Possible Hemlock B.T. (stp.) S 65° E 35 links.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 6/5/52
REGISTERED LAND SURVEYOR