MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 43 NR _ 22 W _

	Delta	COUNTY
DESCRIPTION OF CORNER	Section Corner common to Sec. 1s 17-18-	19-20_
DESCRIPTION OF CORNER	MONUMENT_1" pipe with 4" brass cap	
WITNESSES TO CORNER	12" Soft Maple S 10° W 48	links
	12" Soft Maple N 60° E 33	links
	9" Y. Birch S 30° E 93	links
	"S 20 NBT"	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner from two hemleck stump bettems bearing H 35° W 27 links and S 45° E 18 links. Distance checks very good in all four directions.

Found many eld line blazes east of corner. Found pest 41 links west and 1.14 chs. south set as approximate corner by unknown persons.

SURVEYORS SEAL

SIGNED_ Billy D. Buckles DATE 6/5/57_