FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T. 43N S., R. 22W W.	H-9 &I-9	
2. PROPERTY CONTROLL- ING IN SECTION—	,T		
3. MISCELLANEOUS PROPERTY IN SECTION	,TNEW.		
4. LOT NO , REC	CORDED PLAT		
5. PRIVATE CLAIMS			REGIS

TER OF DEEDS STAMP AND FILING NUMBER

David B. Babbitt _, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on January 26, 1983, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on_____ _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

- A. Description of original monument and accessories and/or subsequent restoration:
- H-9 S 1/4 Corner of Section 22; Marcus McNabb 1929 No description of Cor. Mon. N.B.T.s- Elm 6" N55 E 50'; Basswood 6" S36 W 43.5'.
- I-9 S.E. Sec. Cor. of Sec. 22; Frank Bray R.L.S. 9-21-71 set D.N.R. Mon. 22" W. Pine N43°W 4.9'; 7" H. Maple S7°E 20.5'.
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- H-9 Set on line between the S.E. and S.W. Sec. Cors. of Sec. 22 and 2646.7' Easterly of said S.W. Sec. Cor. as recorded in a record of survey by Marcus McNabb in 1929. This falls exactly in line with an old fence line South. McNabbs N.B.T.s are gone.
- I-9 Found D.N.R. Mon. as set by Frank Bray in 1971. His W. PIne N.B.T. is gone. Rewitnessed Mon. as found.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- H-9 1" pipe 4" aluminum cap; 5" Cedar N39°W 75.3'; 10" R. Maple N16°E 55.6'; 14" Sugar Maple S5°W 57.4'; 6" Sugar Maple S34°W 64.1'.

 I-9 1" pipe 4" aluminum cap; 6" Y. Birch N54°E 87.9'; 12" Y. Birch S77°E 51.5';
- power pole N5 E 21.6'.

SIGNED BY and B. Baffett	DATE 3-7-83	_
SURVEYOR'S MICHIGAN REGISTRATION NO. 21558	(SEAL)	