

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 & 44 N. R. ~~22~~ 23W


Delta and Marquette COUNTY

DESCRIPTION OF CORNER Section Corner for Sections 31|32 T 44 N R 23 W
61 5 T 43 N R 23 W

CORNER MONUMENT 1 1/4" Pipe at Fence Corner

DATE MONUMENT PLACED AND WITNESSED 9-5-61

WITNESSES TO CORNER..... 6" Cedar (S.32) (NBT) N 34° E 30 1/2 links



6" Aspen (S.5) (NBT) S 73° E 43 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-witnessed, pipe at fence corner seems to check well with corners in vicinity.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE April 27, 1961
REGISTERED LAND SURVEYOR
Billy D. Buckler