LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF:	LOCATED IN -:	CORNER CODE NUMBER	DELTA
I. PUBLIC LAND SURVEY_19	T. 43 XX, R. 23 XX	A-8 - B-8	Co.
2. PROPERTY CONTROLL- ING IN SECTION	N. E. S., R. W.		-
	,T		
4. LOT NO, RE	CORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND
			FILING NUMBER of P.A. 74, Michigan P.A. of 1970,
Bureau of Land Management of and 5 above were, in a field survas expressed below and in confe Decree of a Court of law: A. Description of original mone B-8 Center 1/4 confe	r by a decree of a court of law. yey on	Finstructions of the United S Furthermore, that the corner 9, found, recovered, rest ichigan State Board of Registr bsequent restoration: previously establishe	in conformance with regulations tates Department of the Interior, points mentioned in lines 3, 4 ored, established or re-established ation for Land Surveyors or, by a d
B. Description of corner evidend B-8 Set at the int	ce found and/or method applied ersection of the N-S a	in restoring or re-establishing nd E-W 1/4 lines of S	(corner: Section 19
A-8 Set M.P.O.L. b Oliver Iron Mi record and doe appears that i Co. monument f	etween the N.W. and S. ning Co. mon. Nl2°W - s not fit well with th	W. Sec. corners of Se 61.2' from this posit e N.W. and S.W. sec. 40 porth of the error	ec. 19. Found rusted off ion but it is not of corners of Sec. 19. It
C. Description of monument for	corner and accessories establish	ed to perpetuate locating the I	position of the corner:
All vinik, monume	nt N51°W 22.0'		
	N42°E 27.0'		
	\$50°E 5.0' \$22''W 39.1'		
A-8 14" tamarack	N75°W 41.6'		
6" black ash (N24°E 25.4'		
5" black ash			
7" red maple	•		
IGNED BY avid	B. Bakkitt	DATE	12-84
URVEYOR'S MICHIGAN REG	ISTRATION NO	21558	(SEAL)
OR STATE AND UNITED ST	 VTES AGENCIES:		•