Cons. 4047 4/98

## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T\_39 NR\_28\_W\_

	Dickinson COUNTY
DESCRIPTION OF CORNER Section corner common to Sec	ctions 11, 12, 13 and 14.
DESCRIPTION OF CORNER MONUMENT_1" Pipe with 4" I	Brass Cap.
WITNESSES TO CORNER7" Cedar N 44 W 40 I	Links, "S 11 NBT"
_9"_Cedar\$_32_E26_I	Links, "3 13 NBT"
_ Witnessed marked by unknown s	surveyor
9" Cedar N 17 E 23 I	Links
5" Tamarack (dead) S 32 E	22 Links.
DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED	AND IDENTIFIED OR

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from two Tamarack B.T.'s bearing N 20 E, 19 Links and N 65 W, 17 Links. Found scribe marks on both stumps.

Two iron bars and woodbost in proper position.

Corner lies in swamp.

Corner placed and witnessed on 10 December 1958 with H. S. Peterson, District Forester.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 4-29-5

Billy D. Buckles