

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 39. & 40 R27. & 28. W

Dickinson and Menominee . . . . COUNTY

DESCRIPTION OF CORNER Section corner common to sections 1, 6, 31 and 36 .

DESCRIPTION OF CORNER MONUMENT Wood post and 1" Iron Pipe with 4" Brass Cap . . .

WITNESSES TO CORNER 8" Cedar (S6 NBT) S 50° E 21 Links . . . . .

7" Cedar (S1 NBT) S 10° W 10 1/2 Links . . . . .

6" Cedar (S 36 NBT) N 66° W 24 Links . . . . .

6" Cedar (S 31 NBT) N 31° E 31 Links . . . . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was set from Tamarack B. T. (See notes) and was found by Region One Survey crew.

Corner was placed and witnessed October 29, 1959 with Frank J. Bray.

SURVEYORS SEAL

SIGNED Billy D. Buckler . . . . . DATE 4/8/60 . . .  
REGISTERED LAND SURVEYOR  
Billy D. Buckler