

## DEC 1 8 1995

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE

	- '	115	13	-	17	?	**
i (	<del>-</del>	: -	C.	1	L	Ĺ	IJ

		Filing Requiren	nent of Act 74, Mich. P.A.	1970
	orners in kisnon		0 0 1 "	633 NOV 21 /M II: 27
DIC	(County)	Located In:	Corner Code #	5000 1001 Feb. 701 II 6m 1
1. P	ublic Land Survey	T 39N R 29W T R T R T R	K-3	ELECTRICATE PEEDS ELECTRICATE OF THE ENGINEER EACTRICATE OF THE ENGINEER
	roperty Controlling Section	S T R S T R		
	liscellaneous roperty in Section	S T R S T R		Register of Deeds Stamp & File Number
4 1	nt No.	ecorded Plat		
5 Pr	rivate Claims	coorded Fish		A B C D E F G H I J K
0. 1.	TVATO CIANTIS			2 - 6 - 5 - 4 - 3 - 2
				3
ı Rol	art F Parking	in a field survey on	No. 6 10.05	
		uirements of P.A. 74, Michigan P.A. o		
		onformance with regulations and rule		
manua	I of survey instructions	of the United States Departmen	it of the Interior, Bureau of La	and 7
		a Court of Law and/or that the come		
		with the rules of the Michigan Boar dished, re-established, monumented		
	ressed below:	maried, re-established, mondinented	r, re-monumented, recovered, roc	10 30 29 28 27 26
				11
MOLE	on this certificate.	ners, all in the same town and ra	inge, may be recorded	12 31 32 33 34 35
				13
A. D	escription of original n	nonument and accessories and	/or subsequent restoration:	
K	Post J.H. Original Be Beech 10"	orner, Section 2 Mullett, D.S. 1849 aring Trees N65°E 15 Lks. N60°W 15 Lks.		ACCEPTED BY THE DICKINSON COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON 11-20-95 COUNTY REPRESENTATIVE
B. De		idence found and/or method ap	<del>-</del>	lishing corner:
K	-3 No Evidence Corner remo	of Original Corner or ved by recent County R	Accessories Found.	
	Corner resea	arched in 1994 by Sund	berg & Carlson.	
-				

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Southeast Corner, Section 2


Set  $2\frac{1}{2}$  Stamped Dickinson County Remonumentation Monument buried 8" in Shoulder of Road. Corner Re-established from Prior Surveys and Witnesses.

New Witnesses

Power Pole #60-23745 S70°W (M.B.)

Power Pole #95-03574 S81°E (M.B.) Lynn 36" East (M.B.) 71.0' Willow 20" S34°E (M.B.) 158.80'

Corner is 10.3' West of West E.O.M. Var. = ±8°



Signed by

\_\_\_\_ Date Nov. 7, 1995

12027 Surveyor's Michigan License No.\_

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983