## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T\_41 NR 28 W T 40 NR 28 W

			DicginsonCOUNTY
DESCRIPTION	OF	CORNER	Section Corner common to Sections 35,36,4
DESCRIPTION	OF	CORNER	MONUMENT_1" Pipe with 4" Brass cap
WIT TNESSES	то	CORNER	8* Cedar - N 31 W - 32 Links
			8* Cedar - 8 69 W - 17 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Ferestry Division survey crew, while making a partial resurvey of this area. Cermer had been previously located by unknown Surveyor. No original evidence in place, but measurements check good in all directions.

Corner was placed and witnessed July 21, 1954.

SURVEYORS SEAL

SIGNED SIGNED LAND SURVEYOR DATE 2/11/55