

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 40. NR. 28. W.
T. 41. NR. 28. W.

----- Dickinson ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 5, 6, 34 -----

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap -----

WITNESSES TO CORNER 14" Elm - N 26 W - 87 Links -----

12" W. Birch - S 60 E - 89 Links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established, by proportionate measurement, by Forestry Division survey crew, while making a partial resurvey of this area. Good Line Trees 5 ch. West & 9 ch. East.

Corner was placed and witnessed July 21, 1954.

SURVEYORS SEAL

SIGNED Dean C. DeLester DATE 2/11/55
REGISTERED LAND SURVEYOR