MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T_40. NR_28 _ W

	_D_i c k_i n a o n COUNTY
DESCRIPTION OF	CORNER 1/4 corner between 13 and 24
DESCRIPTION OF	CORNER MONUMENT_1" Pipe_with 4" Brass Cap
WITNESSES TO CO	ORNER 9" Hard Maple (1/4s NBT) S 13° E -65-1/2 Links
	8" Hard Maple _ (1/4s BT) _ S 88° E _64 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established midway and on line between two Section Corners. No evidence of original corner.

Corner was placed and witnessed December 9, 1959 with Frank J. Bray.

SURVEYORS SEAL

SIGNED_ Sully E) Sucheles DATE 2/23/60_

Billy D. Buckler