

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 40. NR. 28. W

Dickinson COUNTY

DESCRIPTION OF CORNER Section corner for Sections 13, 14, 23, 24.

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 10" Spruce (S 24 NBT) S 77° E 89 Links

7" Balsam (S 13 NBT) N 35° E 40 Links

5" Maple (S 14 NBT) N 69° W 39 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced at old wood stake and 1/2" Iron Bar placed by unknown surveyor. Found blazed Pine Stub 05 Links to east. There is a skidding road at corner. It is possible any evidence of corner could have been destroyed.

Corner was placed and witnessed May 27, 1969 with Frank J. Bray.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 9/13/60
REGISTERED LAND SURVEYOR
Billy D. Buckler