

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION



# LAND CORNER RECORD

T. 40 N.R. 28 W


Dickinson COUNTY

DESCRIPTION OF CORNER 1/4 Corner for sections 5/8

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 5/24/65 Bray and Hinds

WITNESSES TO CORNER..... 9" Tamarack (1/4S NBT), East, 50 Irs.



10" Spruce (1/4 S NBT) S 10° E, 61½ Irs.

AND

CIRCLE CORNER REGISTERED

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

This Corner was replaced from wood post and point of older poster which check good with stream to west and swamp edge to East. , also checks fairly well with Section Corners to East and West.

**SURVEYOR'S SEAL**

SIGNED Frank J. Bray DATE 6/8/1965  
REGISTERED LAND SURVEYOR