

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

⁴⁰ ²⁸ W
T₄₀ ... NR 29 W ...

Dickinson

... COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 18, 19, 13, 24

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 16" Hemlock S 15° E 70 links

16" Hemlock N 33° E 85 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Cedar stake in ground; traces of older stake in soil.

Distance checks very close to good Corners East and West; North to ledge and stream; South to ledges.

One old cedar tree has been blazed as a witness by unknown persons.

Corner placed and witnessed August 9, 1955.

SURVEYORS SEAL

SIGNED Billy D. Buckles
REGISTERED LAND SURVEYOR

DATE 2/16/56