

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 40. NR. 28. W. . .

----- Dickinson ----- COUNTY

DESCRIPTION OF CORNER 1/4 Section Corner between Sections 8 and 9 -----

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap. -----

WITNESSES TO CORNER ----- 12" Cedar ----- S 84° E ----- 55 links -----

----- 12" Cedar ----- S 25° E ----- 46 links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

1" Iron Pipe in place, set by unknown surveyor.

Traces of several old stakes in soil.

One Hemlock stump bottom in proper position.

Corner placed and witnessed August 4, 1955.

SURVEYORS SEAL

SIGNED

Billy D. Buckler

REGISTERED LAND SURVEYOR

DATE 2/16/56 -----