

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 40. NR. 28. W. . .

----- Dickinson ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 9, 10, 15, 16 -----

DESCRIPTION OF CORNER MONUMENT 1" pipe with 1/2" brass cap set. -----

WITNESSES TO CORNER 10" Elm N 78° W 58 links -----

----- Fence Corner - South 27 links -----  
-----  
-----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner set by unknown surveyor.

Corner is in N. and S. fence line. There are good corners one mile south and 1/2 mile east.

3" Iron Pipe in place.

Corner placed and witnessed December<sup>3,</sup> 1955.

SURVEYORS SEAL

SIGNED

*Billy D. Buckles*

REGISTERED LAND SURVEYOR

DATE 2/23/56