

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD


T. 40 NR. 28 W.

D i s k i n s o n . . . . . COUNTY

DESCRIPTION OF CORNER East 1/8 corner between 13 and 24

DESCRIPTION OF CORNER MONUMENT 1" x 48" Iron Pipe

WITNESSES TO CORNER 5" Hard Maple (BT) S 75° W 19 Links



5" Elm (BT) N 22° E 33 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was established midway between 1/4 corner to west and Section corner from east.

Corner lies on North edge of road.

Corner was placed and witnessed January 27, 1960 with H. S. Peterson, District Forester.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 2/23/60  
REGISTERED LAND SURVEYOR  
Billy D. Buckler