

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 40. NR. 29 W. .

----- DICKINSON ----- COUNTY

DESCRIPTION OF CORNER 1/4 Section Corner between Sections 15 and 22 -----

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap. -----

WITNESSES TO CORNER 9" Cedar S 68° W 21 links. -----

8" Cedar S 54° E 9 links. -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

1/4 Corner set midway and on line between two Section Corners.
No evidence of original corner.

Corner placed and witnessed August 11, 1955.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 1/26/56
REGISTERED LAND SURVEYOR