

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 40. NR. 29. W.

----- Dickinson ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 14, 15, 22, 23

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap

WITNESSES TO CORNER 10" Hard Maple - S S W - 50 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by Forestry Division survey crew, while making a partial resurvey of this Township. Summit of Hill West, Stream crossings East, North and South, as per Gov't. notes. One probable B.T. still in place, badly rotted.

Corner was placed and witnessed July 20, 1954.

SURVEYORS SEAL

SIGNED John C. [Signature] DATE 2/11/55
REGISTERED LAND SURVEYOR