## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T\_41 NR 28 W T 40 NR 29 W

			DickinsonCOUNTY
DESCRIPTION	OF	CORNER	Section Corner common to Sections 32,33 & 1
DESCRIPTION	OF	CORNER	MONUMENT_Im Pipe with 4m Brass cap
WIT TNESSES	то	CORNER	7" Tamarack - N 15 W - 29 Links
			7" Tamarack - S 83 E - 15 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established, by proportionate measurement, by Forestry Division survey crew, while making a partial resurvey of this area. No original B.T.'s evident, but good corners North, Fast and West. Stream crossing Fast checks e.k., as per Gov't. notes.

Corner was placed and witnessed July 22, 1954.

SURVEYOR'S SEAL

SIGNED LAND SURVEYOR DATE 2/21/55