

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 40. NR 29 W. . .

----- Dickinson ----- COUNTY

DESCRIPTION OF CORNER .. 1/4 Section Corner between Sections 13 and 14 ..

DESCRIPTION OF CORNER MONUMENT .. 1" pipe with 4" brass cap ..

WITNESSES TO CORNER .. 12" Cedar .. S 55° W .. 55 links ..

----- 12" Cedar .. S 67° E .. 56 1/2 links ..

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 Section Corner.

Old Cedar stake in soil - 2" iron pipe set by unknown persons.

Dist. South 2.50 chs. to rock bluff checks.

Corner placed and witnessed March 13, 1956.

SURVEYORS SEAL

SIGNED

Billy D. Buckles
REGISTERED LAND SURVEYOR

DATE 3/19/56