MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_40 NR 29 W

	-	Dickinson	COUNTY
DESCRIPTION OF C	ORNER Section Corner	common to Sections 16,	17,20,21
DESCRIPTION OF CO	ORNER MONUMENT_1	Pipe with A" Brass car)
WITTNESSES TO CO	ORNER 12" Hemlock -	N 40 W - 25 Links	
	7" Ceder - N	16 E - 18 Links	
		.	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this Township. Corner had been previously located by unknown. One original B.T. still in place, in poor condition.

Corner was placed and witnessed August 5, 1954.

SURVEYORS SEAL

SIGNED SEAN LAND SURVEYOR DATE 2/10/55