

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. ⁴⁰ NR. ^{29W}

Dickinson

COUNTY

DESCRIPTION OF CORNER North 1/8th corner between sections 8 and 9

DESCRIPTION OF CORNER MONUMENT 3/4th iron bar

WITNESSES TO CORNER 4th Norway pine N 24th E marked X BT

6th rock ledge Marked X with cold chisel

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by single proportionate measurement, by Forestry Division Survey Crew while making a partial resurvey of this township.

Corner was placed and witnessed 9 February 1957.

SURVEYORS SEAL

Henry S. Peterson

Henry S. Peterson

SIGNED

REGISTERED LAND SURVEYOR

2/11/57

DATE