

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T39-40 NR 29 W

Dickinson

COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sec.'s 34-3

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 16" Jack pine S 11° W 170 links
"1/4 S NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-established 1/4 corner midway and on line between two section corners.

No evidence of original corner. 1/4 corner lies in open, burnt pine land.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 11/22/57
REGISTERED LAND SURVEYOR