LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH, P.A.1970

FOR CORNERS OF–:	LOCATED IN–:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. 40 N. ~~S.~~ R. 29 E. ~~W.~~	G 10
2. PROPERTY CONTROLLING IN SECTION 27	T. 40 N. ~~S.~~ R. 29 E. ~~W.~~	3
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. S., R. _____ E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in a field survey on July 11 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner G10: Wood post — **Not found. Old wood post nailed to BT.**
Cedar 8 N58E 9 — **" "**
Cedar 8 N64W 10 — **Probably found.**

Corner 3: Not established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner G10: Corner replaced at record bearing and distance from probable original BT. No marks, but old burned blaze approximately faces corner. Old squared post had been nailed to the BT stump, and the stump is the S'ly terminus of an old N & S fence. Distance N to swamp edge and foot of hill agrees with original record.

Corner 3: Established on line between section corner 20.214 ch. N and 1/4 corner 20.214 ch. S.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Monuments for both corners: 1" I.D. x 36" iron pipe with 4" aluminum cap.

Witnesses for Corner G10: Cedar 9 S42°E (mag.) 22.8 ft. "1/4S, NBT"
Cedar 5 S86°W (mag.) 4.7 ft. "1/4S, NBT"
Cedar 5 N24°W (mag.) 4.0 ft. "1/4S, NBT"

Also squared and scribed a 4" cedar S20°E 1.7 ft.

Witnesses for Corner 3: Ironwood 6 S24°W (mag.) 9.7 ft. "1/16S, BT"
Sugar Maple 9 S35°E (mag.) 27.0 ft. "1/16S, BT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY CHIEF OF SURVEY PARTY Arthur O. Enger MICHIGAN REGISTERED LAND SURVEYOR DATE April 11, 1973

Arthur O. Enger (SEAL)

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. **13581**

Form No. ML M73b
DOUBLEDAY PRCT. & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS