

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 40 N.R. 29 W


Dickinson COUNTY

DESCRIPTION OF CORNER 1/64 corner placed midway and on line between W1/16 corner of sections ~~48~~ and section corner to west.

CORNER MONUMENT 1" Iron pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 7/28/67, Frank J. Bray

WITNESSES TO CORNER..... 7" Cedar (1/64)(BT) North 14 1/2 Links



18" Cedar (1/64)(BT) N 61° W, 20 1/2 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Place midway and on line between section corner to west and the W 1/16 corner to east.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 10/13/67
REGISTERED LAND SURVEYOR