

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES


LAND CORNER RECORD

Dickinson COUNTY
42N
T 41N R 27W

DESCRIPTION OF CORNER W 1/16 corner between Section 33 T42N R27W and Section 4,
CORNER MONUMENT 1" pipe and 4" aluminum cap. T41N R27W.

DATE MONUMENT PLACED AND WITNESSED 6-24-70 with John Fiorucci

WITNESSES TO CORNER..... 16 Cedar (1/16 BT) N11E 18 Lks.



12 Cedar (1/16 BT) S32E 30 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Placed corner on line and midway between Section corner to West and 1/4 corner to East. 10" Tamarack line tree to West 13.60 chains.

SURVEYOR'S SEAL

SIGNED

H. S. Peterson
H. S. Peterson

DATE

6-25-70

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68