

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Dickinson COUNTY  
T 41N R 27W

DESCRIPTION OF CORNER 1/4 corner between Sections 13 and 24

CORNER MONUMENT 1" pipe and 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 6-24-70 with John Florucci

WITNESSES TO CORNER..... Cedar (1/4 S NBT) 11 N33W 16 Lks



Cedar (1/4 S NBT) 7 S 52E 20 Lks

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced corner from original Tamarack bearing tree (14S43W25).  
Old wood post in place. Original bearing tree in excellent condition.  
Scribe marks very plain.

SURVEYOR'S SEAL

*H. S. Peterson*

DISTRIBUTION:

SIGNED H. S. Peterson  
REGISTERED LAND SURVEYOR

DATE 6-25-70

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68