

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Dickinson COUNTY
42N
T 41N R 27W

DESCRIPTION OF CORNER 1/4 corner between Sections 33, T42N R27W and Section 4,
T41N R27W.

CORNER MONUMENT 1" iron pipe and 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 6-17-70 with John Fiorucci.

WITNESSES TO CORNER..... Cedar (1/4 S NBT) 7 S64E 36 1/2 Lks.



Cedar (1/4 S NBT) 9 N20E 7 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Placed corner on line and by proportionate distance from Department marker
1/2 mile to East and 10" Tamarack line tree 33.60 chains to West.

SURVEYOR'S SEAL

H S Peterson

DISTRIBUTION:

SIGNED

H. S. Peterson
REGISTERED LAND SURVEYOR

DATE

6-25-70

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68