

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 41. NR. 28 W. .

DICKINSON

COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 19 and 20

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap.

WITNESSES TO CORNER 1 1/2" Iron Pipe S 75° E 20 links.

6" Black Spruce N 55° E 52 links.

8" Aspen S 23° W 42 links.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

One Yellow Pine (down) in poor condition. One Cedar turnout in proper position. No trace of identifying marks. An old stake in ground in proper position. Corner found by Survey Crew while making a partial re-survey in this area.

Corner placed and witnessed June 2, 1955.

SURVEYORS SEAL

SIGNED

*Billy D. Buckler*  
REGISTERED LAND SURVEYOR

DATE 1/26/56