

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 41. NR. 28. W. . .

----- DICKINSON ----- COUNTY

DESCRIPTION OF CORNER 1/4 Section Corner bet. Sections 17 - 20 -----

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap. -----

WITNESSES TO CORNER 10" Cedar S 89° W 92 links. -----

8" White Birch S 12° E 38 links. -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Cedar and Hemlock stumps in proper position, poor condition. A pile of stones in ground in proper position.

Corner found by Forestry Division Survey Crew while making a partial re-survey of this area.

Corner placed and witnessed July 13, 1955.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 1/23/56  
REGISTERED LAND SURVEYOR