MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_41_ NR_28 W._

			DICKINSON COUNTY
DESCRIPTION	OF	CORNER	1/4 Section Corner bet. Sections 23 - 26
DESCRIPTION	OF	CORNER	MONUMENT 1" pipe with 4" brass cap.
WIT TNESSES	то	CORNER	10" Cedar S 17° W 75 links.
			10" Cedar S 85° E 63 links.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

One Cedar B. T. in poor condition.

Corner found by Survey Crew while making a partial re-survey in this area. Corner placed and witnessed July 11, 1955.

SURVEYOR'S SEAL

SIGNED Silly & Suchlet DATE 1/23/56