Cons. 4047

MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_41 NR_28 W

-	Dickinsen	_ COUNTY
ORNER <u>1/4 section</u> c	erner between sections 24	and 25
RNER MONUMENT_1"	pipe with 4" brass cap	
RNER 6" Red Pine	N 47 W 127 links, marked 1	/4 s nbt
6" Peplar	N 1 W 27 links, marked N	BT
	ORNER _ 1/4 section corner MONUMENT_1" RNER _ 6" Red Pine _ 6" Peplar	Dickinsen ORNER 1/4 section corner between sections 24 ORNER MONUMENT 1" pipe with 4" brass cap RNER 6" Red Pine N 47 W 127 links, marked 1 6" Peplar N 1 W 27 links, marked N

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner placed previously by Ferestry Division survey crew and later pushed out by read improvement work.

Corner placed from stump of peplar NBT N 47 E 41 links placed by B. Buckler, Ferestry Division Surveyor. Corner placed in pile of rocks in cut on West side of County Read.

Cerner placed and witnessed 18 April 1960 with Heward Petter.

SURVEYOR'S SEAL

SIGNED Henry S. Petersen
REGISTERED LAND SURVEYOR

DATE _6/6/60