## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T 41 NR 28 W

			induned COUNT
DESCRIPTION	OF	CORNER	Section Corner common to Sections 30,31,25,36
DESCRIPTION	OF	CORNER	MONUMENT_1" Pipe with 4" Brass cap
WIT TNESSES	то	CORNER	10" Ceder + 8 60 E - 29 Links
			12* Cedar - 8 85 W - 30 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this area. 3 original B.T.'s still in place, in good condition.

Corner was placed and witnessed July 26, 1954.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 2/21/55