## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T\_41 NR 28 W.

			DickinsonCOUNTY
DESCRIPTION	OF	CORNER	1/4 Corner between Sections 25 & 26
DESCRIPTION	OF	CORNER	MONUMENT 1º Pipe with 4º Brass cap
WIT TNESSES	то	CORNER	24" W. Pine - N 28 W - 150 Links
			20* R. Pine - 5 4 E - 107 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this Township. Remains of two original P.T.'s still in place, in poor condition.

Corner was placed and witnessed August 6, 1954.

SURVEYORS SEAL

SIGNED SEAM C. DISTANDE DATE 2/10/55