

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 41 NR. 28 W.

Dickinson COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sec.'s 33-34

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 5" Tamarack S 2° E 11 1/2 links

"1/4 S NBT"

6" Tamarack S 85° E 32 1/2 links

"1/4 S NBT"

7" Tamarack N 11° W 36 links

"1/4 S NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-established 1/4 corner midway and on line between two section corners.

Found no conclusive evidence of original corner.

1/4 corner lies in swamp.

Corner placed and witnessed January 2, 1958.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 1/13/58
REGISTERED LAND SURVEYOR