

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 41 NR. 28 W

Dickinson COUNTY

DESCRIPTION OF CORNER 1/4 corner on south side of Sec. 33 and on 4th correction
line.

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 12" dead Cedar stub S 50° E 7 links
"NET"

12" dead Cedar stub S 58° W 32 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

Re-established 1/4 corner midway and on line between two section corners.

Found no evidence of original corner. 1/4 corner lies in an area which is
flooded by beaver dam.

Corner placed and witnessed January 2, 1958.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 1/13/58
REGISTERED LAND SURVEYOR